ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0070, W0075, W0073, W0089, W0077	NA	Nagappa and Subbarayappa Badavana
Segment No.	**Total Length (m)**	
7/C-W0070/S032943	298.74	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	68.45	77.605645	13.078207	77.606246	13.078017	W0075	DEAD END
2	51.66	77.605520	13.077757	77.605615	13.078215	W0073	W0070
3	65.42	77.605586	13.077635	77.605417	13.077067	W0073	DEAD END
4	47.30	77.605848	13.077560	77.605748	13.077150	W0073	DEAD END
5	65.91	77.606059	13.077532	77.605494	13.077732	M0013	W0075

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads & Drains Asphalting in Nagappa and Subbarayappa Badavana ward no 07 Kodigehalli Sub-Division Yelahanka zone	2500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads & Drains Asphalting in Nagappa and Subbarayappa Badavana ward no 07 Kodigehalli Sub-Division Yelahanka zone	007-15-000015
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/254/2014-15	02/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2015	01/02/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

SAMBASHIVA		0.00
Phone No.	**E-Mail ID**	
9035637741		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
5		basavaraj
Date of Inspection	**Remarks**	
06/08/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0070, W0075, W0073, W0089,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	06/08/2016	05/09/2016	COMPLETED
SE	VASU K M	06/08/2016	05/09/2016	COMPLETED
EE	YARAPPA REDDY	06/08/2016	05/09/2016	COMPLETED
AEE	RAJANIKANTH	06/08/2016	05/09/2016	COMPLETED
AE	BASAVARAJ	06/08/2016	05/09/2016	COMPLETED
AE	BASAVARAJ	06/08/2016	05/09/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0070, W0075, W0073, W0089, W0077